

SITE INSPECTION REVIEW FORM

SITE NAME: Stauffer Chemical

ALIASES: _____

SITE I.D.#: NJD001894229

| <u>ITEM</u> | <u>COMPLETE ?</u> <u>YES</u> | <u>NO*</u> |
|--|---------------------------------|------------|
| SITE LOCATION (INCLUDING MAP) | <u>✓</u> | _____ |
| SITE BACKGROUND | <u>✓</u> | _____ |
| ENVIRONMENTAL SETTING (GEOLOGY, HYDROLOGY, METEOROLOGY, ECOLOGY + LAND USE) | <u>✓</u> | _____ |
| WASTE DESCRIPTION (PRESENCE + CONDITION OF WASTE + WASTE MANAGEMENT UNITS) | <u>✓</u> | _____ |
| LABORATORY RESULTS (CORRELATED TO SAMPLE LOCATION MAP) | _____ | _____ |
| HRS PRE - SCORE (PRELIMINARY + PROJECTED) | <u>✓</u> | _____ |
| POTENTIAL FOR DIRECT CONTACT | <u>✓</u> | _____ |
| CONCLUSIONS + RECOMMENDATIONS | <u>✓</u> | _____ |
| REFERENCES | <u>✓</u> | _____ |

HRS PRE-SCORE: PRELIMINARY SCORE =

37.93

PROJECTED SCORE =

41.90

COMMENTS:

A remedial program is currently being developed
under direction of the USDEP - Division of
Hazardous Waste Management - Deffer Defer
to USDEP

REVIEWED BY:

Jeff Guel

DATE:

5-30-09

*IF ANY ITEM IS LACKING INFORMATION PLEASE DESCRIBE IN COMMENTS